

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	Womack White
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	32.008330332
<b>Longitude:</b>	-97.601697819
<b>Inspected by:</b>	D. Kieninger
<b>Date:</b>	08.03.2010

<b>Sur name :</b>	Womack	<b>Monument Type:</b>	tablet w/base
<b>First Name 1:</b>	Calvin D	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	No

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	broken sunken . tilted

## Recommended Treatment

<p>Mortar tablet monument into slotted base. Epoxy broken pieces back together. Fill cracks with Jahn color matched restorative mortar Safely lift monument from current position Remove old foundation and replace with suitable foundation for monument type and size Level monument base and align with neighboring monuments Remove all failed setting masonry and compounds and replace the</p>	<p>setting material Safely clean monument with appropriate cleaning solution and technique</p>
--	--

**Conservation Priority (1-3): 1** (1 = immediate 2= 1-2 years 3= 2-4 years reassess)

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$101.85	\$250	\$391.85

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008330032</b>
<b>Longitude:</b>	<b>-97.601602438</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	Stringer	<b>Monument Type:</b>	basal
<b>First Name 1:</b>	Nancy	<b>Material Top:</b>	concrete
<b>First Name 2:</b>		<b>Material Base:</b>	concrete
		<b>Footstone</b>	No

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing
			broken .
			sunken

## Recommended Treatment

nique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the setting material  
 Safely clean monument with appropriate cleaning solution and tech-


**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$20	\$245	\$0	\$265

**Comments: a replica stone would be a good idea** lied to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*  
 All information given and recommendations made herein are be-

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008322629</b>
<b>Longitude:</b>	<b>-97.60162164</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	Prine	<b>Monument Type:</b>	tablet w/base
<b>First Name 1:</b>	Jake	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted .

## Recommended Treatment

nique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the setting material  
 Safely clean monument with appropriate cleaning solution and tech-

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$98.75	\$0	\$138.75

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008330075</b>
<b>Longitude:</b>	<b>-97.601669797</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	unknown	<b>Monument Type:</b>	upright w/o base
<b>First Name 1:</b>	unknown	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	No
		<b>Footstone</b>	

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted .
		<b>Posi-</b>	

## Recommended Treatment

nique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the setting material  
 Safely clean monument with appropriate cleaning solution and tech-

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$17.5	\$0	\$57.5

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	Womack White
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	32.00834236
<b>Longitude:</b>	-97.601689024
<b>Inspected by:</b>	D. Kieninger
<b>Date:</b>	08.03.2010

<b>Sur name :</b>	Womack	<b>Monument Type:</b>	upright with base
<b>First Name 1:</b>	CG	<b>Material Top:</b>	marble
<b>First Name 2:</b>	TA	<b>Material Base:</b>	limestone
		<b>Footstone</b>	No

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted .

## Recommended Treatment

nique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the setting material  
 Safely clean monument with appropriate cleaning solution and tech-

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$46.55	\$0	\$86.55

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



**Cemetery:** Womack White

**State:** Texas  
**County:** Bosque  
**City/Comm.:** Morgan

**Latitude:** 32.008401011  
**Longitude:** -97.601663693

**Inspected by:** D. Kieninger

**Date:** 08.03.2010

<b>Sur name :</b>	Womack	<b>Monument Type:</b>	pedestal obelisk
<b>First Name 1:</b>	John A	<b>Material Top:</b>	limestone
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted .

## Recommended Treatment

nique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the setting material  
 Safely clean monument with appropriate cleaning solution and tech-

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$161.25	\$0	\$201.25

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008419943</b>
<b>Longitude:</b>	<b>-97.601734092</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	Cook	<b>Monument Type:</b>	tablet w/base
<b>First Name 1:</b>	Phedory	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted . broken

## Recommended Treatment

<p>Epoxy broken pieces back together. Fill cracks with Jahn color matched restorative mortar</p> <p>Safely lift monument from current position Remove old foundation and replace with suitable foundation for monument type and size Level monument base and align with neighboring monuments Remove all failed setting masonry and compounds and replace the</p>	<p>setting material Safely clean monument with appropriate cleaning solution and technique</p>
---	--

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$123.1	\$175	\$338.1

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008475623</b>
<b>Longitude:</b>	<b>-97.601755277</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	Hornbuckle	<b>Monument Type:</b>	tablet w/base
<b>First Name 1:</b>	Wiley	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing
			tilted .
			broken

## Recommended Treatment

Epoxy broken pieces back together. Fill cracks with Jahn color matched restorative mortar  Safely lift monument from current position Remove old foundation and replace with suitable foundation for monument type and size Level monument base and align with neighboring monuments Remove all failed setting masonry and compounds and replace the	setting material Safely clean monument with appropriate cleaning solution and technique
--	--

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$140.6	\$175	\$355.6

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*



# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	Womack White
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	32.008573048
<b>Longitude:</b>	-97.601723749
<b>Inspected by:</b>	D. Kieninger
<b>Date:</b>	08.03.2010

<b>Sur name :</b>	Burk	<b>Monument Type:</b>	tablet w/base
<b>First Name 1:</b>	P.F.	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted . broken

## Recommended Treatment

Epoxy broken pieces back together. setting material  
 Fill cracks with Jahn color matched restorative mortar Safely clean monument with appropriate cleaning solution and technique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$108.75	\$175	\$323.75

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	Womack White
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	32.008674595
<b>Longitude:</b>	-97.601806275
<b>Inspected by:</b>	D. Kieninger
<b>Date:</b>	08.03.2010

<b>Sur name :</b>	Ligon	<b>Monument Type:</b>	tablet w/base
<b>First Name 1:</b>	John	<b>Material Top:</b>	marble
<b>First Name 2:</b>	Eddie	<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted . broken

## Recommended Treatment

Epoxy broken pieces back together. setting material  
 Fill cracks with Jahn color matched restorative mortar Safely clean monument with appropriate cleaning solution and technique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$235.6	\$175	\$450.6

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008708744</b>
<b>Longitude:</b>	<b>-97.601802821</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	Ligon	<b>Monument Type:</b>	tablet w/base
<b>First Name 1:</b>	Margaret	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing
			tilted .
			broken

## Recommended Treatment

Epoxy broken pieces back together. Fill cracks with Jahn color matched restorative mortar  Safely lift monument from current position Remove old foundation and replace with suitable foundation for monument type and size Level monument base and align with neighboring monuments Remove all failed setting masonry and compounds and replace the	setting material Safely clean monument with appropriate cleaning solution and technique
--	--

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$140.6	\$175	\$355.6

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008688149</b>
<b>Longitude:</b>	<b>-97.601871347</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	Womack	<b>Monument Type:</b>	upright with base
<b>First Name 1:</b>	Susan Wife of AC	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted .
		<b>Posi-</b>	

## Recommended Treatment

nique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the setting material  
 Safely clean monument with appropriate cleaning solution and tech-

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$172.8	\$0	\$212.8

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	Womack White
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	32.008674895
<b>Longitude:</b>	-97.601854562
<b>Inspected by:</b>	D. Kieninger
<b>Date:</b>	08.03.2010

<b>Sur name :</b>	Womack	<b>Monument Type:</b>	upright with base
<b>First Name 1:</b>	Mathew G son of AG & S	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted .

## Recommended Treatment

nique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the setting material  
 Safely clean monument with appropriate cleaning solution and tech-

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$76.55	\$0	\$116.55

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008487298</b>
<b>Longitude:</b>	<b>-97.601796502</b>
<b>Inspected by:</b>	<b>D. Kieninger</b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	Womack	<b>Monument Type:</b>	upright with base
<b>First Name 1:</b>	Infant	<b>Material Top:</b>	concrete
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	No

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted . broken

## Recommended Treatment

Epoxy broken pieces back together.  
 Epoxy broken pieces back together.  
 Epoxy broken pieces back together. Fill cracks with Jahn color  
 matched restorative mortar  
 Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for  
 monument type and size  
 Level monument base and align with neighboring monuments

Remove all failed setting masonry and compounds and replace the  
 setting material  
 Safely clean monument with appropriate cleaning solution and tech-  
 nique

**Conservation Priority (1-3): 1** (1 = immediate 2= 1-2 years 3= 2-4 years reassess)

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$20	\$46.55	\$275	\$341.55

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



**Cemetery:** Womack White

**State:** Texas  
**County:** Bosque  
**City/Comm.:** Morgan

**Latitude:** 32.008381445  
**Longitude:** -97.601803857

**Inspected by:** D. Kieninger

**Date:** 08.03.2010

<b>Sur name :</b>	Deason	<b>Monument Type:</b>	basal
<b>First Name 1:</b>	Febba	<b>Material Top:</b>	concrete
<b>First Name 2:</b>		<b>Material Base:</b>	concrete
		<b>Footstone</b>	No

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted . broken

## Recommended Treatment

nique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the setting material  
 Safely clean monument with appropriate cleaning solution and tech-

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$20	\$140	\$0	\$160

**Comments:** a replica stone would be a good idea  
 All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008427609</b>
<b>Longitude:</b>	<b>-97.601850189</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	White	<b>Monument Type:</b>	tablet w/base
<b>First Name 1:</b>	infant dau of OD & George	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted .

## Recommended Treatment

nique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the setting material  
 Safely clean monument with appropriate cleaning solution and tech-

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$82.5	\$0	\$122.5

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*





# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	Womack White
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	32.008496172
<b>Longitude:</b>	-97.601861576
<b>Inspected by:</b>	D. Kieninger
<b>Date:</b>	08.03.2010

<b>Sur name :</b>	White	<b>Monument Type:</b>	tablet w/base
<b>First Name 1:</b>	Loren	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted . broken

## Recommended Treatment

Epoxy broken pieces back together. setting material  
 Fill cracks with Jahn color matched restorative mortar Safely clean monument with appropriate cleaning solution and technique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the


**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$135	\$175	\$350

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.00851675</b>
<b>Longitude:</b>	<b>-97.601875467</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	McDonald	<b>Monument Type:</b>	tablet w/base
<b>First Name 1:</b>	Ella	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted .

## Recommended Treatment

nique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the setting material  
 Safely clean monument with appropriate cleaning solution and tech-


**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$161.25	\$0	\$201.25

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008562424</b>
<b>Longitude:</b>	<b>-97.601884233</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	Goss	<b>Monument Type:</b>	heart
<b>First Name 1:</b>	Jack son of JS & M	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	standing tilted .

## Recommended Treatment

<p>remove old pins</p> <p>Safely lift monument from current position</p> <p>Remove old foundation and replace with suitable foundation for monument type and size</p> <p>Level monument base and align with neighboring monuments</p> <p>Remove all failed setting masonry and compounds and replace the setting material</p>	<p>Safely clean monument with appropriate cleaning solution and technique</p>
---	---

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$88.1	\$100	\$228.1

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.0085785</b>
<b>Longitude:</b>	<b>-97.601887262</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	Harris	<b>Monument Type:</b>	upright with base
<b>First Name 1:</b>	Ruth Miller	<b>Material Top:</b>	marble
<b>First Name 2:</b>	Wife of J.W.	<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	Posi- tilted broken .

## Recommended Treatment

Epoxy broken pieces back together. Fill cracks with Jahn color matched restorative mortar  Safely lift monument from current position Remove old foundation and replace with suitable foundation for monument type and size Level monument base and align with neighboring monuments Remove all failed setting masonry and compounds and replace the	setting material Safely clean monument with appropriate cleaning solution and technique
--	--

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$154.95	\$175	\$369.95

**Comments: repair on base** lied to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*  
 All information given and recommendations made herein are be-

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008624868</b>
<b>Longitude:</b>	<b>-97.601897431</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	unknown	<b>Monument Type:</b>	upright with base
<b>First Name 1:</b>	unknown	<b>Material Top:</b>	limestone
<b>First Name 2:</b>		<b>Material Base:</b>	No
		<b>Footstone</b>	

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	.

## Recommended Treatment

nique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the setting material  
 Safely clean monument with appropriate cleaning solution and tech-

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$0	\$23.1	\$0	\$23.1

**Comments: Find top** lied to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*  
 All information given and recommendations made herein are be-

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008654668</b>
<b>Longitude:</b>	<b>-97.601907815</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	Womack	<b>Monument Type:</b>	grave cover
<b>First Name 1:</b>	Abner P.	<b>Material Top:</b>	limestone
<b>First Name 2:</b>		<b>Material Base:</b>	No
		<b>Footstone</b>	

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	level
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	.

## Recommended Treatment

Safely clean monument with appropriate cleaning solution and technique

**Conservation Priority (1-3): 1** (1 = immediate 2= 1-2 years 3= 2-4 years reassess)

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$0	\$0	\$40

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008681737</b>
<b>Longitude:</b>	<b>-97.601901638</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	Womack	<b>Monument Type:</b>	tablet w/base
<b>First Name 1:</b>	Tilitha	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	No

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	Posi- sunken tilted .

## Recommended Treatment

<p>Mortar tablet monument into slotted base.</p> <p>Safely lift monument from current position</p> <p>Remove old foundation and replace with suitable foundation for monument type and size</p> <p>Level monument base and align with neighboring monuments</p> <p>Remove all failed setting masonry and compounds and replace the setting material</p>	<p>Safely clean monument with appropriate cleaning solution and technique</p>
---	---

**Conservation Priority (1-3): 1** (1 = immediate 2= 1-2 years 3= 2-4 years reassess)

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$69.65	\$75	\$184.65

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*



# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008655152</b>
<b>Longitude:</b>	<b>-97.601955641</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	White	<b>Monument Type:</b>	upright with base
<b>First Name 1:</b>	Jno L.	<b>Material Top:</b>	marble
<b>First Name 2:</b>	Elizabeth W.	<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	sunken tilted .

## Recommended Treatment

<p>Carefully remove excess mortar.</p> <p>Safely lift monument from current position</p> <p>Remove old foundation and replace with suitable foundation for monument type and size</p> <p>Level monument base and align with neighboring monuments</p> <p>Remove all failed setting masonry and compounds and replace the setting material</p>	<p>Safely clean monument with appropriate cleaning solution and technique</p>
---	---

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$258.1	\$100	\$398.1

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*



# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008534914</b>
<b>Longitude:</b>	<b>-97.60191125</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	White	<b>Monument Type:</b>	upright with base
<b>First Name 1:</b>	Pierce	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	broken tilted .

## Recommended Treatment

<p>Mortar tablet monument into slotted base.</p> <p>Safely lift monument from current position</p> <p>Remove old foundation and replace with suitable foundation for monument type and size</p> <p>Level monument base and align with neighboring monuments</p> <p>Remove all failed setting masonry and compounds and replace the setting material</p>	<p>Safely clean monument with appropriate cleaning solution and technique</p>
---	---

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$161.25	\$75	\$276.25

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*



# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008509345</b>
<b>Longitude:</b>	<b>-97.601901133</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	White	<b>Monument Type:</b>	upright with base
<b>First Name 1:</b>	Katie B.	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	broken tilted .

## Recommended Treatment

Build a concrete slotted base Mortar tablet monument into slotted base.  Safely lift monument from current position Remove old foundation and replace with suitable foundation for monument type and size Level monument base and align with neighboring monuments Remove all failed setting masonry and compounds and replace the	setting material Safely clean monument with appropriate cleaning solution and technique
--	--

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$91.25	\$75	\$206.25

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	Womack White
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	32.008487047
<b>Longitude:</b>	-97.601893703
<b>Inspected by:</b>	D. Kieninger
<b>Date:</b>	08.03.2010

<b>Sur name :</b>	White	<b>Monument Type:</b>	upright with base
<b>First Name 1:</b>	Robert	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	.

## Recommended Treatment

nique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the setting material  
 Safely clean monument with appropriate cleaning solution and tech-

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$88.1	\$0	\$128.1

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008466992</b>
<b>Longitude:</b>	<b>-97.601888651</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	White	<b>Monument Type:</b>	upright with base
<b>First Name 1:</b>	Jno M.	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	Posi-tilted .

## Recommended Treatment

nique

Safely lift monument from current position  
 Remove old foundation and replace with suitable foundation for monument type and size  
 Level monument base and align with neighboring monuments  
 Remove all failed setting masonry and compounds and replace the setting material  
 Safely clean monument with appropriate cleaning solution and tech-

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$166.85	\$0	\$206.85

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*

# Texas Cemetery Restoration LLC



<b>Cemetery:</b>	<b>Womack White</b>
<b>State:</b>	Texas
<b>County:</b>	Bosque
<b>City/Comm.:</b>	Morgan
<b>Latitude:</b>	<b>32.008491088</b>
<b>Longitude:</b>	<b>-97.601999763</b>
<b>Inspected by:</b>	<b><i>D. Kieninger</i></b>
<b>Date:</b>	<b>08.03.2010</b>

<b>Sur name :</b>	White	<b>Monument Type:</b>	tablet w/base
<b>First Name 1:</b>	Daniel	<b>Material Top:</b>	marble
<b>First Name 2:</b>		<b>Material Base:</b>	limestone
		<b>Footstone</b>	Yes

<b>Soiling Type:</b>	soiling biological microbes	<b>Levelness:</b>	unlevel
<b>Soiling Severity 1-5:</b>	4	<b>Monument Position:</b>	sunken tilted .

## Recommended Treatment

Mortar tablet monument into slotted base. Build a concrete slotted base  Safely lift monument from current position Remove old foundation and replace with suitable foundation for monument type and size Level monument base and align with neighboring monuments Remove all failed setting masonry and compounds and replace the	setting material Safely clean monument with appropriate cleaning solution and technique
--	--

**Conservation Priority (1-3): 1 (1 = immediate 2= 1-2 years 3= 2-4 years reassess)**

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$40	\$82.5	\$75	\$197.5

**Comments: Find base or make** lied to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*  
 All information given and recommendations made herein are be-



## Texas Cemetery Restoration LLC

		<b>Cemetery:</b>	Womack White
		<b>State:</b>	Texas
		<b>County:</b>	Bosque
		<b>City/Comm.:</b>	Morgan
		<b>Latitude:</b>	
		<b>Longitude:</b>	
		<b>Inspected by:</b>	<i>D. Kieninger</i>
		<b>Date:</b>	08.03.2010

<b>Sur name :</b>		<b>Monument Type:</b>	
<b>First Name 1:</b>		<b>Material Top:</b>	
<b>First Name 2:</b>		<b>Material Base:</b>	
		<b>Footstone</b>	

<b>Soiling Type:</b>		<b>Levelness:</b>	
<b>Soiling Severity 1-5:</b>		<b>Monument Position:</b>	<b>Posi- tion:</b>

### Recommended Treatment

**Conservation Priority (1-3):** (1 = immediate 2= 1-2 years 3= 2-4 years reassess)

**Pricing: Price is valid until 6/30/2011**

Cleaning	Leveling w/footstone	Repairs	Total + tax
\$	\$	\$2775	\$7696.15

**Comments:** All information given and recommendations made herein are believed to be accurate, but not guaranteed. *Texas Cemetery Restoration LLC*